

At AAON, we are committed to continuously enhancing our products through regular software updates. The release notes below provide an overview of updates, features, and hot fixes introduced in the most recent software versions. This document may not include all changes, especially minor adjustments or security enhancements. Features may vary depending on user settings or environment.

Note: AAON software updates are rolled out in phases to monitor performance and adjust as needed before being available to all users. If you are unable to update your software but see new release notes, please check back soon for future availability. It is the responsibility of the building manager to ensure all devices remain current with the latest compatible software version.

RM454-Z SS1194 Software release notes	
Software version 1.45 – Current Version	January 28, 2026
<ul style="list-style-type: none"> • Improvements: <ul style="list-style-type: none"> ○ Three unsafe suction pressure trips within one hour will trigger a circuit lockout until the power is cycled. ○ Added a reheat percentage screen to the status menu for modules three and six. • Hot Fix: <ul style="list-style-type: none"> ○ The VFD compressors would not stage on if both of the tandem compressors failed. 	
Software version 1.44	October 06, 2025
<ul style="list-style-type: none"> • Improvements <ul style="list-style-type: none"> ○ Increased the default oil boost duration from 60 seconds to 90 seconds. ○ When selecting a single condenser for A&B, it will automatically apply to a second set of VFD circuits C&D. 	
Software version 1.43	July 19, 2024
<ul style="list-style-type: none"> • Improvements <ul style="list-style-type: none"> ○ Adjustments to the board/ebus address in hidden screens are now applied automatically. ○ The pressure setpoints (such as low suction pressure or unsafe suction pressure) now match the 454b conversion. 	