

At AAON, we are committed to continuously enhancing our products through regular software updates. The release notes below provide an overview of updates, features, and hot fixes introduced in the most recent software versions. This document may not include all changes, especially minor adjustments or security enhancements. Features may vary depending on user settings or environment.

**Note:** AAON software updates are rolled out in phases to monitor performance and adjust as needed before being available to all users. If you are unable to update your software but see new release notes, please check back soon for future availability. It is the responsibility of the building manager to ensure all devices remain current with the latest compatible software version.

|  |                   |
|--|-------------------|
| <b>RSMD</b><br><b>SS1067</b><br><b>Software release notes</b>  |                   |
| Software version 3.37 – Current Version<br><ul style="list-style-type: none"><li>Hot fix to Water Source Heat Pump A1B1 configuration. For this hot fix to be applied, the version 2.20 software release must be applied to the VCCX.</li></ul>  | April 24, 2025    |
| Software version 3.36<br><ul style="list-style-type: none"><li>Hot fix to a low suction alarm: changed the value the alarm is checked against, from 30 to adjusted MinPosition</li></ul>   | March 24, 2025    |
| Software version 3.35<br><ul style="list-style-type: none"><li>Hot fixes to the following:<ul style="list-style-type: none"><li>Changed Condenser percent “Analog Out” value</li><li>Defrost functionality: When there is a fault on compressor one, allow compressor two to defrost</li></ul></li></ul> | February 12, 2025 |
| Software version 3.34<br><ul style="list-style-type: none"><li>Minor improvements to dehumidification sequence</li><li>Hot fix to water source heat pump</li></ul>   | December 9, 2024  |