At AAON, we are committed to continuously enhancing our products through regular software updates. The release notes below provide an overview of updates, features, and hot fixes introduced in the most recent software versions. This document may not include all changes, especially minor adjustments or security enhancements. Features may vary depending on user settings or environment.

Note: AAON software updates are rolled out in phases to monitor performance and adjust as needed before being available to all users. If you are unable to update your software but see new release notes, please check back soon for future availability. It is the responsibility of the building manager to ensure all devices remain current with the latest compatible software version.

VCCX-IP SS1186 Software relea	ise notes	
Software versio	on 2.22 – Current Version	May 20, 2025
Hot fix	xes for the following:	
0	The supply fan now cycles during vent mode	
0	Addressed several concerns with mode determination and mode enabling	
Software versio	on 2.20	April 24, 2025
NEW	FEATURE: Heat Pump Proof of Water Flow Check	•
0	Supported Units: VCCX2, VCCX-IP	
0	Details: If circuits A1 and B1 both register with no proof of water flow, an alarm will be set for both circuits. This lets VCCX go off and allows auxiliary heat to come on	
 Minor 	improvements to:	
0	RSM Emergency Stop Mode	
0	Updated the ModBus Delay to 20ms for the SAT, RAT, and OAT digital senso	rs. This update
	addresses an issue with the Relative Humidity percentage sometimes show	ring up incorrectly
0	Added latching to Flush Mode	
0	The Cool Mode Coil Temp setpoint can now go to 70°F Max	
0	 RSMs can now be put into Emergency Stop Mode instead of requiring the RS in an Emergency Shutdown event 	Ms to be power cycled
 Hot fix 	x for the following:	
0	Water Source Heat Pump A1/B1 configuration (Note: for this hot fix to be ap software release must be applied to the VCCX)	plied, the version 2.20
Software versio	on 2.16	January 28, 2025
 Hot fix 	xes for the following:	
0	Trend logs	
0		
0	Unoccupied Economizer operation	
Software versio	on 2.15	December 9, 2024
Hot fix	xes for the following:	
0	VAV Broadcasts	
0	Dual circuit reheat	
0	Economizer to follow BACnet SAT Setpoint	

 "Restore Defaults" functionality when swapping between SS1186 and SS1188 on the same VCCX-IP controller board