

ECat Software Upgrade to Version <u>6.0.359/5.0.359</u>

Release date: July 7, 2025

The install password for ECat v5 CHILLERSAIRHANDLERS17216FANS

https://www.aaon.com/ecat-download

Note: If you need ECat 6 login credentials, they can be provided through registration@aaon.com. There is only one ECat 6 update file, it works for both initial installation and updating the software.

ECat 6 Updates

Direct ECat 6 Download Link

Single Sign-On

ECat 6 has been updated to Single Sign-On (SSO) so that it uses the same password and login information as Rep Central and My AAON. An email was sent last Monday with login instructions. If you have not followed that process and logged into Rep Central, please do that first before trying to log into ECat 6 V359 with SSO.

H3, V3, and M2 R-410A DX Air Handling Units

The last day to order H3 or V3 R-410A DX AHU is July 18^{th.} The M2 option has been increased to \$999,999 pricing in ECat 5 in this release. The H3/V3 option will be increased to \$999,999 pricing in the V360 ECat 6 release.

Bug Fixes: Re-Run units affected

ΑII

- 1. Adjustments have been made to the code to improve the speed of the Repricing function.
- 2. Fixed issue with recycled units showing on the Order Form. Note that these recycled units did not appear in any of the other reports in the paperwork.
- 3. Fixed the endless repricing loop in V358 that occurred when older R-410A RN config strings that were not up to date were imported.
- 4. Forecasting Bulk Status Update adjusted to be compatible with more screen display resolutions by adjusting accessibility of Save button.
- 5. Job Management Fixed the option to change the order of units in a scenario with Right Click then Move Rows.

Rooftop Units

- 6. RN/RQ/RZ Fan selection (F3, F5, and F6) and breaker size (F13B and F13C) are not selectable in the feature string anymore. This corrects an issue created in V358. Verify that your current selections are valid
- 7. RQ Hot water coils are no longer selectable on units with horizontal discharge (F2=G).
- 8. RN Fixed issue with gas and auxiliary electric heat not loading all valid options for the initial heater into the drop-down menus.

- 9. RN/RQ/RZ Removed return air temperature sensor and duct static sensor from the controls submittal report for units selected with factory provided Single Zone VAV controls.
- 10. RZ Changed space sensor on submittals for RZ MHGR from analog to digital.

Split Systems

- 11. H3 Fix issue with split gas heat displaying "The heat staging data is invalid" unnecessarily. The gas heater must be reselected with the same option and saved to fix the issue. Note that this error message is not always invalid.
- 12. V3 Added detail to V3 D-E electric heat cabinet submittal to note that front discharge is standard.
- 13. H3/V3 Fixed visual bug where F22 shows \$0.00 for all options on H3/V3s selected as split systems. The Worksheet and Total Price in the Reports include the actual cost of that feature, so this makes no change to the overall unit cost or reports.

Self-Contained Units

14. SA - Units now allow the rows for hot water coils to be selected on the Unit Conditions page.

ECat 5 Updates

Product Updates

- 1. M2 R-410A DX air handling units have been increased to \$999,999 pricing because we can no longer manufacture this option after December 2025.
- 2. M2-036 Return fan module has been updated to use an RDM- when 2 fans are selected and an RDB- when 1 fan is selected. This corrects the electrical rating information (FLA, MCA, MOP) when a single fan was selected in a RDM module.
- 3. M2-036 Hot water coil face area corrected on the rating sheet to show 36 square feet instead of 18.

Please continue to provide feedback on ECat 6. Our dedicated AAON ECat Team is here to support you. Contact ecatsupport@aaon.com with questions, comments, and bugs.