

At AAON, we are committed to continuously enhancing our products through regular software updates. The release notes below provide an overview of updates, features, and hot fixes introduced in the most recent software versions. This document may not include all changes, especially minor adjustments or security enhancements. Features may vary depending on user settings or environment.

Note: AAON software updates are rolled out in phases to monitor performance and adjust as needed before being available to all users. If you are unable to update your software but see new release notes, please check back soon for future availability. It is the responsibility of the building manager to ensure all devices remain current with the latest compatible software version.

RSMD-GH SS1172 Software release notes	
Software version 1.21 – Current Version <ul style="list-style-type: none"> Minor improvements were made to the following: <ul style="list-style-type: none"> The fault timer is now cleared immediately after an emergency shutdown is cleared Reduced the hold duration of the Unit at Max signal for the VCCX from 60 seconds to 10 seconds Hot fixes to the following: <ul style="list-style-type: none"> Fixed the diagnostic menu displaying incorrect screens The compressor now faults when the compressor running signal is lost 	May 20, 2025
Software version 1.20 <ul style="list-style-type: none"> Improvements to VCCX Emergency Shutdown Command functionality 	January 30, 2025
Software version 1.18 <ul style="list-style-type: none"> Improvement to staging performance of 40-ton units Improvements made to allow the VCCX to reset compressor stage timers Hot fix to High Head Pressure safeties 	January 30, 2025
Software version 1.17 <ul style="list-style-type: none"> Hot fix to discharge temperature setpoint maximum value 	January 30, 2025
Software version 1.16 <ul style="list-style-type: none"> Improvements to secondary staging routine for compressors Minor adjustment to outside right envelope safety of slowing condenser fan to minimum per lab Hot fix to relay status bitfield 	January 30, 2025