

At AAON, we are committed to continuously enhancing our products through regular software updates. The release notes below provide an overview of updates, features, and hot fixes introduced in the most recent software versions. This document may not include all changes, especially minor adjustments or security enhancements. Features may vary depending on user settings or environment.

Note: AAON software updates are rolled out in phases to monitor performance and adjust as needed before being available to all users. If you are unable to update your software but see new release notes, please check back soon for future availability. It is the responsibility of the building manager to ensure all devices remain current with the latest compatible software version.

FAN COMM Controller-SR SS1189 Software release notes	
Software version 1.02 – Current Version <ul style="list-style-type: none">• Improvement<ul style="list-style-type: none">○ Increased the delay time to 20 seconds for failure to slow, speed up, start, or stop alarms.<ul style="list-style-type: none">▪ If the type of alarm changes, the timer will reset.	March 26, 2026
Software version 1.01 <ul style="list-style-type: none">• Improvement<ul style="list-style-type: none">○ Added a check to ensure operations are fully stopped before starting the fans.	March 17, 2026
Software version 1.00 <ul style="list-style-type: none">• Initial release	January 22, 2026